








VAŽNO – PRE UPOTREBE PAŽLIVO PROČITAJTE I SAČUVAJTE UPUTSTVO
IMPORTANT – READ CAREFULLY – RETAIN FOR FUTURE REFERENCE
WICHTIG – SORGFÄLTIG LESEN UND AUFBEWAHREN
ВАЖНО – ПРОЧИТИТЕ ВНИМАТЕЛЬНО – СОХРАНИТЬ ДЛЯ ДАЛЬНЕЙШЕГО ИСПОЛЬЗОВАНИЯ




K13-EG
 LWH -1307x487x878
 14.08.2019











0 5 10 15 20 25 30 35 40 45 50 55 60 65 70 75 80 mm




- | | | | | | | | | | | |
|------------|-----------|------------|------------|------------|-----------|------------|-----------|-----------|-----------|------------|
| x6 | x4 | x4 | x28 | x16 | x6 | x12 | x6 | x6 | x1 | x12 |
| x14 | x4 | x12 | x18 | | x6 | | | | | |
| | x3 | x2 | x3 | x2 | x6 | x4 | | | | |
| | | | x4 | x3 | x1 | x1 | | | | |










20




0108





0095

3.5x20




21




0121

1.4x25

22




0102



14080

23




0113




0065

Ø15x10


24




25




26



27



28



29

